Firmware update on Index V5 embosser

Firmware update from Internet (wired or WiFi network connection):

- press MENU on the control panel of the V5 embosser
- key down to User service and press OK
- key down to Firmware update and press OK
- select Firmware update from internet by pressing OK
- latest firmware is now installed. This process takes 1-10 minutes and is completed with a restart of the embosser.

Firmware update from USB media:

- download and extract the update file to a USB media
- place the USB media in the USB host port of the embosser
- press MENU on the control panel
- key down to User service and press OK
- key down to Firmware update and press OK
- key down to Firmware update from USB media and press OK
- latest firmware is now installed. This process takes 1-10 minutes and is completed with a restart of the embosser.

It is not possible to downgrade the firmware on the embosser.